

Dart Aerospace Ltd. 1270 Aberdeen St Hawkesbury, ON K6A 1K7 Canada

ENGINEERING CHANGE REQUEST

Tel (613) 632-5200 Fax 613 632-5246

ECR 138 Date Opened: 1/11/21 11:19 AM Requested By: El-Khalil, Hussam Tooling/DSK/GSE Drawing Change Responsible Engineer: Fuentes, Roberto Type: Priority: High Requester*: El-Khalil, Hussam Status: **Under Review** DE Approver*: Shepherd, David Reason: Lee, Michael Expense: 1000 ECR Lead*: Drouin, Steven Target Date: Responsible for Task: Drouin, Steven **Execution Date: ECR Approval No:** RE (R&D): **BRIEF RBW6405G11931-3G - fit issue DESCRIPTION**: Status Note: **DESCRIPTION/ ADR** Customer reported a fit issue with the tool. CONTENT**: Attached is some measurements taken compared to Leonardo's tool. **CUSTOMER APPROVALS Customer Visible Customer Approval Required** Customer **Customer Approved ATTACHMENT PAGES Document Name Document Note** Comparatif MYANMAR - TOUSSUS (002).pdf pictures.pdf **PARTS Part** Part No Rev **Status** Name Type **Customer Part Special Comments Documents** RBW6405G11931-On Tail Rotor Slider Sub-RBW6405G11931-**Bushing Removal &** 3G hold assembly 3G Replace RBW6405G11931-3G RBW6405G11931-3G RBW6405G11931-3G RBW6405G11931-3G RBW6405G11931-3G RBW6405G11931-3G RBW6405G11931-3G **INVENTORY DISPOSITION Part No Revision** Material No | Current Inventory Qty **Purchasing On-Order Qty Qty Scheduled for Production** RBW6405G11931-3G 0 Quarantine Update PO only when drawing Update Jobs only when drawing 0 approved approved **ACCOUNTING JOBS Accounting Job No** Type Group **Status** SE CAD Red Barn Sustain Engineering Active

EFFECTS

Effect Group	Effects
2. ECR Lead Assessment - Impacted Docs & Output	Drawing Change Required
ECR Lead Assessment - Status During ECR	Active - No Under Review, UR - Full Under Review
4. Production Type	In-house production, Outsourced/Purchased Part
Sustaining Cost Grouping	Poor Quality